

Multi-axis Turning Projects and Wood Recommendations

Frank B. Penta
Chapel Hill, NC
woodspriteturnings.com



Blank Sizes

The sizes of the blanks listed below are recommended for a chuck with # 2 jaws, except for the 1 1/2" diameter blanks for the birdhouse perch which will require a smaller set of jaws.

1 Multi-axis box on a pedestal with a multi-axis top

Multi-axis pedestal


2 1/2" x 2 1/2" x 6"

Box

3" x 3" x 3"

Top for box

3" x 3" x 4"



2 Multi-axis birdhouse on a pedestal with a multi-axis top

Multi-axis pedestal

3" x 3" x 6"

Birdhouse body

2" x 2" x 3"

Top for birdhouse

3" x 3" x 3"

Perch for birdhouse

1/2" x 1/2" x 2"



3 Multi-axis bottle stopper

Blank

2" x 2" x 3"



4 Bottle stopper jig

Jig

2" x 2" x 2"

Bolt

3/8" x 1 1/2"



5 Multi-axis birdhouse ornament

Birdhouse body

2" x 2" x 3"

Top for birdhouse

2 1/2" x 2 1/2" x 4"

Finial for birdhouse

2" x 2" x 4"

Perch for birdhouse

1/2" x 1/2" x 2"

